

## SERVICE BULLETIN – 01/OCTOBER 2007

### SP 405-605 NEW COUPLING SPRING

Starting from the following Serial Numbers:

SP 405      s/n 1958

SP 605      s/n 1901

The previous Spring of 2 mm chord section used on Coupling Kit Part Number **060359 01**, **see photo below**, has been replaced with a little bit larger one of **2,5 mm** chord section, in order to have a higher vertical load pushing down the upper part of the coupling and avoid any possible undesired rising up, during the normal operation of the gear reducer.



The new Coupling Kit is exchangeable with former one and will be supplied from now on, in place of the former one under the same Part Number.