

S I m A G

Via Risorgimento, 4 - 20017 Mazzo di Rho (Mi) Italy - Tel: +39.02.93900215 - Fax: +39.02.93900226

Web site : www.simag.it e-mail sales : sales@simag.it e-mail service : service@simag.it

SERVICE BULLETIN – 01/APRIL 2003

SD 80 - SD 125 - SD 210 SC 70 - SC 120 - SC 210 SCR 120

NEW CURTAIN S. S. BRACKET

Starting from the following serial number:

SD 80	s/n	554831
SD 125	s/n	952445
SD 210	s/n	090947
SC 70	s/n	002997
SC 120	s/n	001777
SC 210	s/n	000011
SCR 120	s/n	001786

The previous s. s. curtain bracket has been replaced with a new one, as shown at the pictures below.

The differences are:

- small bended bottom portion to avoid splashing of water.
- closure of the reetangular hole at the two opposite side of the s.s. bracket.

The new curtain assy is perfectly exchangeable with the previous one and is available under the same part number.

