

SERVICE BULLETIN – 01/OCTOBER 2004

SD 18

NEW POSITION OF THE CLEANING SWITCH

Starting from the following serial number:

SD 18 s/n 6521

The Cleaning Switch has been rotated up side down as shown on photos below.



The new position of the Cleaning Switch avoids the wrong commutation to the cleaning position during the installation of the frontal panel.